

GOVERNMENT OF ANDHRA PRADESH
ABSTRACT

Public Servants – Roads & Buildings Department – Disciplinary proceedings initiated against Sri K. Mahender, Superintending Engineer (R&B), the then Superintending Engineer (R&B) Circle, Ongole as he failed to monitor/supervise properly the work of construction of ROB at Rayavaram Village of Guntur-Nandyal Section and R&B Road of Podili-Markapur Road in Prakasam District – Further action dropped and also warned- Orders – Issued.

=====
TRANSPORT, ROADS & BUILDINGS (VIG.I) DEPARTMENT

G.O.Rt.No. 37

Dated.16-01-2011.
Read the following:-

- 1) Memo.No.284/VC(6)/2010-1, dt.07.12.2010 of the Engineer-in-Chief (R&B), Admn., & N.H., A.P., Hyderabad.
- 2) From Sri K. Mahender, SE (R&B), the then SE (R&B) Circle, Ongole, representation dated 12.1.2011.

ORDER:

Article of charge was issued in the reference 1st read above, to Sri K. Mahender, Superintending Engineer (R&B), the then Superintending Engineer (R&B) Circle, Ongole, as he failed to monitor/supervise properly the work of Construction of ROB at Rayavaram Village in lieu of L.C.No.236 at Railway Km.143/10-12 of Guntur-Nandyal Section and R&B Road at K.M.37.2 of Podili-Markapur Road in Prakasam District, due to which 13 slabs of ROB are executed with deficit reinforcement.

2. Sri K. Mahender, Superintending Engineer (R&B), in the reference 2nd read above has submitted representation denying the charge, and requested that he may kindly be exonerated from the charge, and to drop further action against him.

3. Government, after careful examination of the matter, observe that Sri K. Mahender, Superintending Engineer (R&B), has checked measured only two slabs with reference to the quantities entered in the M.Book with those actually executed in site and there are no discrepancies and considering his jurisdiction of entire district and work load and by taking a lenient view decide and hereby drop further action against him; and, also warn him in respect of work of failure to monitor/supervise properly the work of construction of ROB at Rayavaram Village in lieu of L.C.No.236 at Railway Km. 143/10-12 of Guntur-Nandyal Section and R&B Road at K.M.37.2 of Podili- Markapur Road in Prakasam District.

4. The Engineer-in-Chief (R&B), Administration shall take further necessary action in the matter.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

**S.P.SINGH
PRINCIPAL SECRETARY TO GOVERNMENT**

To
Sri K. Mahender, Superintending Engineer (R&B), **through** the Engineer-in-Chief (R&B) Administration & N.H., A.P., Hyderabad.
The Engineer-in-Chief (R&B) Administration & N.H., A.P., Hyderabad.

Copy to:

The Secretary, Andhra Pradesh Vigilance Commission Hyderabad.
The General Administration (V&E) Department, BRK Bhavan, Hyderabad.
SF/SC.

//FORWARDED BY ORDER//

SECTION OFFICER